



Floor Plan Option 1



OPTION 1:

(Estimated Cost \$ 800,000)

ADDRESSES THESE CRITICAL BUILDING NEEDS:

- Inefficient and aged boiler
- Water damaged electrical panels
- Ongoing basement water intrusion
- Ongoing roof leaks at entry way
- Inefficient and ineffective water heater
- Cold, uninviting and unwelcoming Friendship hall
- Crowded, inefficient lounge space
- Outdated heat controls
- Inefficient and barely operable windows throughout education wing
- Poor air circulation and heat control in Education wing


WHAT WE GAIN:

- New boiler, electrical panels
- Improved lighting, HVAC controls
- Fully remodeled and enlarged bathrooms with showers; additional accessible unisex bathroom
- Fully redesigned welcome area that ties Worship Hall with Friendship Hall
- Fully integrated AV system between Friendship Hall and Worship Hall
- Warm, inviting, and more hospitable Friendship Hall for more events and activities. Increased storage and better overflow space.
- Refurbished offices
- Updated education wing finishes
- Energy efficient active ventilation system for education wing

NEXT GENERATION MINISTRY OPPORTUNITIES:

- Enhancing our hospitality – especially on Sunday morning.
- Ensuring the operational future of the building for the next generation.
- Significantly improving our efficiency in energy use.

FLOOR PLAN OPTION 1



ARCHITECTURE
ENGINEERING
INTERIOR DESIGN

